

Vivak HT Sheet

Product Data

Troubleshooting Guide for Thermoforming Parts Made From VIVAK™ HT Sheet		
Problem	Possible Cause	Suggested Solution(s)
Crazed, cracked or brittle parts	<ul style="list-style-type: none"> ■ Poor mold design ■ Sheet forming temp. too low 	<ul style="list-style-type: none"> ■ Increase mold radii to equal sheet thickness ■ Increase heat settings and/or time in oven
Webbing during forming process	<ul style="list-style-type: none"> ■ Sheet too hot ■ Complex mold design ■ Rate of vacuum too fast ■ Uneven heating of sheet ■ Poor mold design ■ Poor mold layout 	<ul style="list-style-type: none"> ■ Decrease sheet temperature ■ Use female mold design ■ Use plug and/or pressure assisted forming ■ Decrease rate and time of applied vacuum ■ Check oven heaters for "hot spots" or bad elements ■ Increase radii and draft angles ■ Spacing between molds should be approximately 2" x depth of draw or height of molded part
Nonuniform sheet sag	<ul style="list-style-type: none"> ■ Uneven oven heating 	<ul style="list-style-type: none"> ■ Check oven heaters and adjust accordingly ■ Check for colder air drafts around forming area
Poor material distribution	<ul style="list-style-type: none"> ■ Uneven oven heating ■ Uneven clamp pressures ■ Deep drawn parts 	<ul style="list-style-type: none"> ■ Check oven heaters and adjust accordingly ■ Check for air drafts around forming area ■ Check clamp pressures and adjust ■ Use plug or pressure assist
Poor detail or part definition	<ul style="list-style-type: none"> ■ Sheet too cold ■ Poor mold design ■ Insufficient vacuum ■ Uneven sheet temperatures ■ Vacuum release too soon ■ External cooling applied too soon 	<ul style="list-style-type: none"> ■ Increase sheet temperature ■ Increase radii, draft angles, spacing, etc. ■ Check vacuum pumps, increase if necessary ■ Check oven heaters and adjust ■ Check for air drafts ■ Increase timing to vacuum release ■ Increase time to external cooling application
Poor surface finish/defects/pinholing	<ul style="list-style-type: none"> ■ Dirty mold ■ Mold surface defects ■ Vacuum holes too large ■ Vacuum rate/amount too high ■ Mold mark-off 	<ul style="list-style-type: none"> ■ Clean mold with air/damp dust-free cloth ■ Sand and/or polish mold surface ■ Decrease size of vacuum holes ■ Decrease rate and/or amount of vacuum ■ Vapor hone or lightly sand mold surface
Sticking to mold	<ul style="list-style-type: none"> ■ Draft angle too small ■ Radii too small ■ Mold too hot 	<ul style="list-style-type: none"> ■ Increase draft angle $\geq 5^\circ$ ■ Increase radii to equal sheet thickness ■ Reduce mold temperature if possible
Voids or bubbles in sheet	<ul style="list-style-type: none"> ■ Sheet too hot ■ Excessive sheet moisture 	<ul style="list-style-type: none"> ■ Decrease heating time and/or oven temperature ■ Dry sheet @ 80°C, 2-4 hours
Part warpage	<ul style="list-style-type: none"> ■ Insufficient cooling of part ■ Mold too cold 	<ul style="list-style-type: none"> ■ Allow part to cool longer prior to mold release ■ Increased mold temperature to allow slower cooling

Vivak HT Sheet


Product Data

Troubleshooting Guide for Thermoforming Parts Made From VIVAK™ HT Sheet continued

Problem	Possible Cause	Suggested Solution(s)
Material pulling from frames	<ul style="list-style-type: none"> ■ Sheet too cold ■ Insufficient/uneven clamp pressure 	<ul style="list-style-type: none"> ■ Increase sheet temperatures ■ Increase/equilibrate clamp pressures
Trimming Difficulties	<ul style="list-style-type: none"> ■ Improper blade selection ■ Incorrect blade speed 	<ul style="list-style-type: none"> ■ Routers: slotting cutter, carbide tipped, 0.062 decimal kerf, 4-wing (i.e. Whiteside part #6700B) ■ Router Bits: Minimum 1/4", 2 fluted preferred, 3-4 flutes for larger bits ■ Band Saw: Minimum 6 teeth/inch ■ Jig Saws: Minimum 10 teeth/inch ■ Table Saws: contact Sheffield's customer service at 800-254-1707 ■ Band Saws: contact Sheffield's customer service at 800-254-1707 ■ Routers: Use 20-25,000 RPM Router speed
Chipping/cracking during cutting	<ul style="list-style-type: none"> ■ Inadequate clamping of parts ■ Saw blade tooth gap too large ■ Dull blade or shear 	<ul style="list-style-type: none"> ■ Increase/equilibrate clamp pressure ■ Choose blade with more teeth/inch ■ Replace blade/sharpen sheet

Figure 1: Radius Design

Stress-Concentration Factor



The curve gives an indication of the proper radius to be used for given wall thickness (courtesy—S.P.J. Plastics Engineering Handbook)

Critical Constraints

- “Like many clear plastics, VIVAK HT can be notch sensitive. As explained in Figure 1, the minimum internal radii for notched sensitive is 1/2 the nominal wall thickness. To obtain the best formed part from VIVAK HT, it is suggested that internal radii of 3/4–1 times the nominal wall thickness be used when designing the mold and/or forming the part.”
- Larger radii distributes stress uniformly.