#### 1. Identification

Product Name: MAKROLON MARINE 5 CLEAR-A00, SMOOTH / SMOOTH

Material Number: 87390803

Chemical Family: Thermoplastic Polymer Sheet

**Use:** For the production of plastic sheet products

#### 2. Hazards Identification

#### **GHS Classification**

This product is not hazardous in the form in which it is shipped by the manufacturer.

**GHS Label Elements** 

Signal word: Warning

Hazard statements: If fine particles are generated during further processing, handling or by

other means, product may form combustible dust concentrations in air.

# 3. Composition/Information on Ingredients

## **Hazardous Components**

There are no hazardous components above the relevant concentration limits according to OSHA HazCom 2012.

# 4. First Aid Measures

# **Most Important Symptom(s)/Effect(s)**

Acute: Contact with heated material can cause thermal burns., Gases and fumes evolved during the



thermal processing or decomposition of this material may irritate the eyes, skin or respiratory tract.

## **Eye Contact**

In case of contact, flush eyes with plenty of lukewarm water.

#### **Skin Contact**

Cool melted product on skin with plenty of water. Do not remove solidified product. Get medical attention if thermal burn occurs.

#### Inhalation

Move to fresh air in case of accidental inhalation of dust or fumes from overheating or combustion.

#### **Ingestion**

Get medical attention.

#### 5. Firefighting Measures

Suitable Extinguishing Media: Water fog, Dry chemical, Carbon dioxide (CO2), Foam

**Unsuitable Extinguishing Media: High Pressure Water Streams** 

#### **Fire Fighting Procedure**

Firefighters should be equipped with self-contained breathing apparatus to protect against potentially toxic and irritating fumes.

### **Hazardous Decomposition Products**

By Fire and Thermal Decomposition: ; Phenol Carbon oxides, Hazardous decomposition products due to incomplete combustion

# Unusual Fire/Explosion Hazards

Toxic and irritating gases/fumes may be given off during burning or thermal decomposition. Avoid generating dust: fine dust dispersed in air in sufficient concentrations and in the presence of an ignition source is a potential dust explosion hazard.

#### 6. Accidental Release Measures

#### **Spill and Leak Procedures**

If molten, allow material to cool and place into an appropriate marked container for disposal. Sweep up and shovel into suitable containers for disposal. Dust deposits should not be allowed to accumulate on surfaces, as these may form an explosive mixture as they are released into the atmosphere in sufficient concentrations. Avoid dispersal of dust in the air (e.g., cleaning dust from surfaces with compressed air).

# 7. Handling and Storage

# **Handling/Storage Precautions**

Handle in accordance with good industrial hygiene and safety practices. Wash thoroughly after handling. Minimize dust generation and accumulation. Routine housekeeping should be instituted to ensure that dust does not accumulate on surfaces. Solid particulate can generate electrical charging during operations such as unloading from containers and pneumatic transfer. Provide adequate precautions, such as electrical grounding and bonding, where conductive equipment is involved.

Page 2 of 6

PLASTICS, INC. Service.

It's what we deliver.

**Storage Period:** 

None.

**Storage Temperature** 

**Maximum:** 49 °C (120.2 °F)

**Storage Conditions** 

Containers should be tightly closed to prevent contamination with foreign materials and moisture.

**Substances to Avoid** 

None known.

#### 8. Exposure Controls/Personal Protection

The recommendations in this section should not be a substitute for a personal protective equipment (PPE) assessment performed by the employer as required by 29 CFR 1910 Subpart I.

#### **Exposure Limits**

Country specific exposure limits have not been established or are not applicable

Any component which is listed in section 3 and is not listed in this section does not have a known ACGIH TLV, OSHA PEL or supplier recommended occupational exposure limit.

### **Industrial Hygiene/Ventilation Measures**

General dilution and local exhaust as necessary to control airborne vapors, mists, dusts and thermal decomposition products below appropriate airborne concentration standards/guidelines, especially during cutting, grinding and high heat operations.

# **Respiratory Protection**

Although no exposure limit has been established for this product, the OSHA PEL for Particulates Not Otherwise Regulated (PNOR) of 15 mg/m3 - total dust, 5 mg/m3 - respirable fraction is recommended. In addition, the ACGIH recommends 3 mg/m3 - respirable particles and 10 mg/m3 - inhalable particles for Particles (insoluble or poorly soluble) Not Otherwise Specified (PNOS).

#### **Hand Protection**

Ensure gloves remain in good condition during use and replace if any deterioration is observed.

Wear heat resistant gloves when handling molten material.

# **Eye Protection**

Safety glasses with side-shields

#### **Skin Protection**

No special skin protection requirements during normal handling and use.

#### **Additional Protective Measures**

Employees should wash their hands and face before eating, drinking, or using tobacco products. Educate and train employees in the safe use and handling of this product. Purgings should be collected as small flat thin shapes or thin strands to allow for rapid cooling.



# 9. Physical and Chemical Properties

State of Matter:solidAppearance:SheetColor:ClearOdor:Odorless

Odor Threshold: No Data Available PH: No Data Available

**Melting Point:** 220 - 230 °C (428 - 446 °F)

**Boiling Point:** No Data Available Flash Point: No Data Available **Evaporation Rate:** No Data Available Flammability: No Data Available Lower explosion limit: No Data Available **Upper Explosion Limit:** No Data Available Vapor Pressure: No Data Available Vapor Density: No Data Available

**Density:** ca. 1.2 g/cm<sup>3</sup> @ 20 °C (68 °F) (DIN 53479)

**Relative Vapor Density:**No Data Available **Specific Gravity:**No Data Available

**Solubility in Water:** insoluble

Partition Coefficient: n- No Data Available

octanol/water:

**Auto-ignition Temperature:**  $> 450 \, ^{\circ}\text{C} \, (842 \, ^{\circ}\text{F})$ **Decomposition Temperature:**  $>= 380 \, ^{\circ}\text{C} \, (716 \, ^{\circ}\text{F})$ 

Fumes evolved by overheating during improperly processing or by

burning may be injurious to health.

**Softening point:** 150 - 160 °C (302 - 320 °F)

**Dynamic Viscosity:** not applicable **Kinematic Viscosity:** No Data Available

#### 10. Stability and Reactivity

#### **Hazardous Reactions**

Hazardous polymerisation does not occur.

# **Stability**

Stable

#### **Materials to Avoid**

None known.

#### **Conditions to Avoid**

Generation of dust clouds.

# **Hazardous Decomposition Products**

By Fire and Thermal Decomposition: Phenol; Carbon oxides, Hazardous decomposition products due to incomplete combustion

# 11. Toxicological Information

**Likely Routes of Exposure:** Inhalation

Skin Contact



Eye Contact

#### **Health Effects and Symptoms**

**Acute:** Contact with heated material can cause thermal burns., Gases and fumes evolved during the thermal processing or decomposition of this material may irritate the eyes, skin or respiratory tract.

# Toxicity Data for: MAKROLON MARINE 5 CLEAR-A00, SMOOTH / SMOOTH

No data available for this product.

# **Carcinogenicity:**

No carcinogenic substances as defined by IARC, NTP and/or OSHA

# 12. Ecological Information

#### Ecological Data for: MAKROLON MARINE 5 CLEAR-A00, SMOOTH / SMOOTH

No data available for this product.

# 13. Disposal Considerations

#### **Waste Disposal Method**

Waste disposal should be in accordance with existing federal, state and local environmental control laws.

# 14. Transportation Information

# **Land transport (DOT)**

Non-Regulated

# Sea transport (IMDG)

Non-Regulated

# Air transport (ICAO/IATA)

Non-Regulated

#### 15. Regulatory Information

# **United States Federal Regulations**

US. Toxic Substances Control Act: Excluded: Article. Cuttings and regrind are listed on the TSCA

inventory, and therefore can be resold.

No substances are subject to TSCA 12(b) export notification requirements.

# US. EPA CERCLA Hazardous Substances (40 CFR 302) Components:

None

#### SARA Section 311/312 Hazard Categories:



Non-hazardous under Section 311/312

US. EPA Emergency Planning and Community Right-To-Know Act (EPCRA) SARA Title III Section 302 Extremely Hazardous Substance (40 CFR 355, Appendix A) Components: None

US. EPA Emergency Planning and Community Right-To-Know Act (EPCRA) SARA Title III Section 313 Toxic Chemicals (40 CFR 372.65) - Supplier Notification Required Components: None

# US. EPA Resource Conservation and Recovery Act (RCRA) Composite List of Hazardous Wastes and Appendix VIII Hazardous Constituents (40 CFR 261):

Under RCRA, it is the responsibility of the person who generates a solid waste, as defined in 40 CFR 261.2, to determine if that waste is a hazardous waste.

## **State Right-To-Know Information**

The following chemicals are specifically listed by individual states; other product specific health and safety data in other sections of the SDS may also be applicable for state requirements. For details on your regulatory requirements you should contact the appropriate agency in your state.

The concentrations reported below in units of parts per million (ppm) or parts per billion (ppb) are maximum values.

#### Massachusetts, New Jersey or Pennsylvania Right to Know Substance Lists:

Weight percent	Components	CAS-No.
>=1%	Bisphenol A Polycarbonate	25971-63-5
<b>&gt;−10</b> / <sub>4</sub>	Richard A Polycarbonata	CASH is a trade

>=1% Bisphenol A Polycarbonate CAS# is a trade secret

# Massachusetts Right to Know Extraordinarily Hazardous Substance List:Weight percentComponentsCAS-No.<=3 ppm</td>Methylene Chloride75-09-2

# California Prop. 65:

Warning! This product contains chemical(s) known to the State of California to be Carcinogenic. Female reproductive toxin.

Weight percentComponentsCAS-No.<=3 ppm</td>Methylene Chloride75-09-2Trace elementBisphenol A80-05-7

